


Southeast Afghanistan Water Resources Assessment: Bank Erosion Site in Matun Area, Shamal Province



Printing Date: Sunday, May 31, 2009 4:25 PM
Prepared By: Henry Shovic (hshovic@montana.edu)
Dept. of Ecology, Montana State University
Coordinate System:
WGS 1984 UTM Zone 42N
File: SEAF_WatershedBankErosion700Scale.mxd

Matun Area: bank erosion example site.
Contours are 5 m. Color imagery from Digital Globe (c).
Location is 69 50 51.10E, 33 26 30.19 N
Elevations are from a 5 m DEM.



South-East Afghanistan Water Resources Assessment

USGS